

Department of Energy

P.O. Box 550
Richland, Washington 99352

95-PCA-440

ÀUG 2 1 1995

Mr.—Moses N. Jaraysi
200 Area Unit Supervisor
Nuclear Waste Program
State of Washington
_Department_of_Ecology
1315 West Fourth Avenue
Kennewick, Washington 99336

Mr. Douglas R. Sherwood
Hanford Project Manager
U.S. Environmental Protection Agency
712 Swift Boulevard, Suite 5
Richland, Washington 99352

Dear Messrs. Jaraysi and Sherwood:

HANFORD FACILITY DANGEROUS WASTE PART A PERMIT APPLICATION, FORM 3s, FOR THE PLUTONIUM-URANIUM EXTRACTION (PUREX) PLANT, REVISION 6 (WA7890008967) (TSD: TS-2-6), AND FOR THE PUREX STORAGE TUNNELS, REVISION 3 (WA7890008967) (TSD: S-2-1)

Enclosed are the Hanford Facility Dangerous Waste Part A Permit Application (Part A), Form 3s, for the PUREX Plant, Revision 6, and for the PUREX Storage Tunnels, Revision 3. The two Part A, Form 3s, have been revised to support new mixed waste storage activities associated with the transport and storage of mixed waste in the PUREX Storage Tunnels and PUREX Plant from various ansite sources. The PUREX Plant will only serve as a temporary staging area for waste accumulation prior to storage in the PUREX Storage Tunnels.

The primary revision to both the PUREX Plant and PUREX Storage Tunnels Part A, Form 3s, has been the addition of Dangerous Waste Numbers to existing Process Code SO5—(storage-miscellaneous): These Dangerous Waste Numbers for the PUREX Plant include DO05 (barium), DO10 (selenium), DO11 (silver) and WTO2 (State-only, toxic for light mineral oil) and DO05 (barium), DO10 (selenium), and WTO2 (State-only, toxic for light mineral oil) for the PUREX Storage Tunnels. Also, language has been included that better reflects the storage activities associated with current and anticipated PUREX Plant and PUREX Storage Tunnels operations.

In addition, State-only designations WTO2 (toxic, dangerous waste) and WPO1 (persistent, extremely hazardous waste) for the fluorothene polymer presently stored in Tunnel Number 2, have been removed. The removal of these designations is based upon the solid nature of the fluorothene polymer which precludes the ability to ingest this material.

AUG 1995

RECEIVED

EDMC

CO E

Messrs. Jaraysi and Sherwood 95-PCA-440

-2-

These changes to the Part A, Form 3s, were made in compliance with Washington Administrative Code 173-303. This regulation requires the submittal of a revised Part A, Form 3, that addresses the identification of a previously unidentified dangerous waste to be stored at a treatment, storage, and/or disposal (TSD) unit under interim status.

Should you have any questions regarding the PUREX Plant and PUREX Storage Tunnels Part A, Form 3s, please contact Mr. C. E. Clark of the U.S. Department . ----of:Energy;:Richland-Operations-Office cm-(509) 376-9333 or Mr. R. C. Bowman of the Westinghouse Hanford Company on (509) 376-4876.

James E. Rasmussen, Director Environmental Assurance, Permits,

and Policy Division

DOE Richland Operations Office

EAP: EMM

William T. Dixon, Director Environmental Services

Westinghouse Hanford Company

Enclosures:

- 1. Hanford Facility Dangerous Waste Part A Permit Application. ____ Form_3, for the PUREX Plant. Revision 6
 - 2. Hanford Facility Dangerous Waste --- Part-A Permit Application, Form 3, for the PUREX Storage Tunnels, Revision 3

-_-cc.w/encls:

Administrative Record

---EDMC;- H6-08

- D. Duncan EPA
- R. Bowman, WHC
- R. Jim, YÍN
- R. Julian, Ecology
- D. Lundstorm, Ecology
- D. Powaukee, NPT
- S. Price, WHC
- J. Wallace, Ecology
- J. Wilkinson, CTUIR

cc w/o encls:

W. Dixon, WHC

ENCLOSURE I

lease print or type in the unshaded areas only Willin areas are spaced for elite type, i.e., 12 character/inch).

		~																MT. T.	A 11112			
FORI 3				DANG	ERO	us was	3T	Εŀ	PE	RI	VΙ	T	ΑF	PI	_1C	ATION	WA	7 8 9	0 0 0		6	7
FOR C	IFF	ൎ	AL I	USE ONLY													•					
APPL	C/	ΑTK	<u>C</u> N	DATE RECEIVED							· .				¢	OMMENTS						
APT	ΠŪ	YE	<u>v</u>	(mo.,day,& yr.)			_					_					-					
u_ EE	107	<u> </u>	2.0	EVISED APPLICATION			—															_
					A or B	below (mark one	box	i oni	y) to	indi	icate	e wi	hethe	er the	e is t	he first application you are a	ubmittle	for your	acility or	a revi-	ed	
.U. NU	MTN	967	M 3	section above.		· · · · · · · · · · · · · · · · · · ·						A/S	TATE	: I.D.	Nun	the first application you are a nber, or if this is a ravised ap	plication,	, enter you	r facility	e EPA/	STA1	E
A. FI	KS.	_		ICATION <i>(place an "X"</i>		•						c.W.										
	L	نــ	r. i	EXISTING FACILITY (S	ee insti omplete	ructions for defin item below.)		of '	THÍS	.ang	rak	ज्या है)	7.			2. NEW FAC						
	[MÇ	П		R EXIST	TING FACILITIES.	PR	jΛiD	E TI	HE D	ATE	E (m	10., <u>d</u>	lay,	yr.)	MO. DAY		FOR NEW	THE DAT	E		
	[0	1			N BEGAN OR TH	ıE D	A IE	CON	15 []	rUC'	1101	u CO	MM	enCE			(mo., day, TION BEG, EXPECTED	AN OR IS	PERA-		
9 05	بر	<u>_</u> _	ᅻ	PLICATION Iplace an	 	nw sad complete	, e.	214-	ند (2000	,							EXPECTEL	TO BEG	N_		
o. KĒ		_		•			. 			7 6	•		-				'ARAH'	c iv ivi ben:	MET			
101	IX 1. FACILITY HAS AN INTERIM STATUS PERMIT PROCESSES - CODES AND CAPACITIES																					
A . PR	CC	£89	8 CC	20E - Enter the code for	rom the	list of process of	ode	امط و	ow 1	that	best	t de	serib	es e	reh r	recess to be used at the fac	Hity To	7 1500	<u>ningidad</u>	for en	arles-	
006	ies	s. II	f me	ore lines are needed, e uding its design capac	nter the	e code(s) in the s	:psc :	e pro	wide	M. I	lt a p	proa	3048 /	will b	HO US	ed that is not included in the	list of c	odes below	, then de	recuibe	the	' .}
•			-	vang its aesign capac ESIGN CAPACITY - For	•									f +b -	par -	-				-		
				SIGN CAPACITY - For • Enter the amount.	. wach ĉ	ANG GRIBING GIA	JIUF	ert A	enti	⊶ ពើ	, ÇĒ	-µ4C	⊶r¥ ū	. int	μισί							
					MATER :	entered in select	יום מ	() e	nt	th-	البيع	. i-	DW +F	he II-	t of	unit measure codes below th	السممام جو	haa sha	h at		فسعا	
2. 1	UN Oni	ly t	he u	MEASURE - For each a units of measure that a	reliste	d below should b	1 (1) 10 (1)	ied.	,ıcd?	u1 6	-UU(ift	om U	.w III	. 01	mar measure codes below th	.e. G080/1	was the Un	.c of mea	wurd ti	. Des	
					PRO-	APPROPRIATI	Ę ŲŅ	ITS_	OF							•	PRO-		OPRIATE			
			Pf		CODE	MEASURE FO	n IT VPA	Ϋ́	دد						_	PROCESS	CODE	MEAS BC	URE FOR BIGN CAI	ACITY	-32	}
Sto	raç	ğe:		 		······································	-			- '					Treat	tment:						•
CO	NŢ	AIN	1ER	(barrel, drum, etc)	S01 S02	GALLONS OR L	ITER	S							TAN	K	T01	BALLON	IS PER D	AY OR		}
WA	.K	ΪĒΙ	PILE	—	502 503	CUBIC YARDS (CUBIC METERS	DR								SUR	FACE IMPOUNDMENT	TO2	GALLON	PER DAY	AY OR		
SÜ	RF	AĈ	E IM	IPOUNDMENT	S Ô4	GALLONS OR L		Ŝ	· ·						INCI	NERATOR	Tos	TONS P	PER DAY ER HOUR TOMS PE	OR LLC.	p.	
	•	*al:					 _						•					GALLOR	ER HOUR TONS PE IS PER H PER HOU	OUR O	R R	
			L N	VELL	D80 -D81	GALLONS OR LI -AGRE-FEET (the									отн	ER (Use for physical, chemic	al, T04	GALLON	es PER Da			
	۔ ۔			· · · · · · · · ·	-	would gover and	e <u>as</u> i otj	/#_te							proc	ER (Use for physical, chemic hal or biological treatment essee not operating in tanks,		LITERS	PER DAY	11		-
ĻAI	ŊО	, AP	PLI	CATION	D82	OR HECTARE-M ACRES OR HEC	抚	ES							atore	toe impoundments or inciner. L. Describe the processes in	•					1
00	EA	NC	DISP	POSAL	D83	GALLONS PER (DAY Y	OR							the i	space provided; Section III-C.	J					
SUI	RF.	ACI	E IM	POUNDMENT	D84 NOT OF	GALLONS OR L	ITER	\$	٠							NIT OF						
1 100 4		٥F	ME	· Mi	INIT OF EASURI CODE			JNIT	<u>ر</u>	ME^	31 m	ìF			ME	NIT OF EASURE CODE UN	T 05 100	A es me		UNIT	URE	
. =	-	<u> </u>				- ···	_		-								IT OF ME			CO	JE Ž	.
LIT	ER	ON:	• • •	**************************************		,	j	ON	K	TIK.	ĵû.	• • •	orie	• • •		AC HE	TARE-M	IETER		• • • •	∷ĝ	
ČŅ	BK L!	M	ETE	AS RS ER DAY	8	Ì	Ğ	'nΨ	ONS	K.	N HC	ĮŲŔ	۱	• • •	• • • •	V AC	CTARES				∷ å	
			- : 1													wi: A facility has two stores water that can burn up to 20	e tenka,	one tank o	187			
	_	_	Ť			ier den held 400 IGN CAPACITY	gall	-114.	TM	180	<u></u>					. B. PROCESS D			····	\top		-
_N 4	CF	PRI	아	·		AVIII	2.	UNIT	ᆔ,	FC	OR CIAI	,	1 11	A.	35	J. I MUESS U		. w 1944 1 T	2. UNIT		FOR	.
-U-	1101	m ii	ist		AQUNT		SI	UNIT MEA JRE	· '	OFFI US ON	SÉ.		.ī.Ml	CO	DE n kar	1, AMOU		-	OF MEA	· ~	FICIA USE	١
		ove		/spe	icify)		/e	nter ide/	ļ	UN		ļi	N B	201	ve)	(specify)	,		(enter	1 '	NLY	
- 1	_		#				F	7	上	<u> </u>		=		-	т.			7.00		+		=
K-1 3	5	0	2	60	00			G	\perp		\sqcup		5									
X-2	Ţ	0	3		20			E	\int			J	6		\int					\prod	\prod	
1 7		0	1	392,1	167			٧					7		I					\prod]	
2 5	1	0	2	1,239,7	733			L	\prod				8		I					\prod	\prod	
3 5		0	5	4	134			С					9		T			_		\prod		
4	1	1					T	T	T			-	10		. _	_				7†		\exists
							_			4										1 1	1 1	l t

Con	tirk	ئجن	i fro	m th	front.					•								
M.	PR	oc	E88	ES (c	ontinued)													
C,	SP/	A CI	E FC	R AC	DITIONAL PROCESS CODES OR FO	O AC	ESCRI	BING	ΙOΊ	THE	RP	'nÖ	CES	SS	(oode	°TO	4"}. F	FOR EACH PROCESS ENTERED HERE INCLUDE DESIGN CAPACITY
																		-
																		•
																		-
																		-
																		· ·
							-											•
											R	EF	ER	Ì 1	TO P	AĜ	Ē Ŝ	•
																		•
					-													
																	- "	•
																		•
					•	-	-											
					OF DANGEROUS WASTES						_							
A. 1)A)	NG.		US V	/ASTE NUMBER - Enter the four dip ter which are not lieted in Chapter	173	303 W	irom /AC,	90	apt ler	ier i the	173 fot	-30: # di	igit İgit	WAC N	or e	that	sted dangerous waste you will handle. If you handle t describes the characteristics and/or the toxic con-
-1				er u	ese dangerous wastes.													·
	'01 '	\$8	City of	itara:	BYUAL QUANTITY - For each listed Harietic or toxic conteminant enter Haracteristic or conteminant.	was in	te enti colum	n A	esti esti		ener Co t	the	e stir tota		ite the	dne	ingth a	of that waste that will be handled on an annual basis. of all the non-listed waste(s) that will be handled which
c. ţ	JNI Ire:	T)F N	IEAS	URE - For each quantity entered in	colu	mn 8 •	nter	the	un	nit a	ıf m	16 34	w	e code	. U	nks of	of measure which must be used and the appropriate codes
•					ENGLISH UNIT OF MEASURE		CO	DE									METR	RIC.UNIT OF MEASURE CODE
_					POUNDS			<u> </u>				-					KH,QQ	GRAMS K
					TONS			Т										
!! •	la:	g iqo	ty re riate	deni	s use <u>any other unit of measure for</u> lity or specific gravity of the waste	qua:	ntity, t	he u	nite	of	me	126 L	ife n	mu		ÖÑŸ	erted i	i into one of the required units of measure taking into account the
D. P	RO	CE	SSE	s	•													
1.	. PF	RO	CES	s co	DES:													
	Fo	ا بر	iste	dan	gerous waste: For each listed dang	perou adás	M Was	te e	iter	ed :-:-:	in c	elu 1	mn .	A	select	the	code(i	(s) from the list of process codes contained in Section III to
	Fo	or r	on-	listed ii) to										-	ered in	Col	umn A the no	A, select the code(s) from the list of process codes contained in on-listed dangerous wastes that possess that characteristic or
						20.00	oodes.	. N	mor		e 6	-	led:	: I	11 Ente	w th	a (frat	st three as described above; [2] Enter "900" in the extreme right
	-80)K-	ei it	em n	/-U(1); and (3) tinter in the space p	rovid	no bei	p ag	4,	CTM	• W	10 II		Dér	r and t	10	dditior	onal code(s).
	_																	ass in the space provided on the form.
_ N	OT um	E:	DAI she t	NG EF	IOUS WASTES DESCRIBED BY MOI described on the form as fellows:	RE T	HAN O	NE	AAC	1GE	BRO	US	WA	4 51	TE NUI	48E	R - Da	angerous wastes that can be described by more than one Wasta
4.		Se	set	688	of the Bangarous Waste Numbers a	nd e	nter it	în o	oitan		Á.	Ōn	the	• • •	nme fin	. 0	mplet	ete columns B, C, and D by estimating the total annual quantity of
					nd describing all the processes to I					-	-			-				**************************************
- 2,			OVE.	and	of the next line enter the other Da make no other entries on that line .	r/Ger	ons M	aste	Nu	mb	opr t	itat	car	n b	ie USBC	to	descrit	ribe the waste. In column D(2) on that line enter "included with
3.		Re	peat	step	2 for each other Dangerous Waste	Nur	mber ti	hat c	an I	be	y ze	d to	de	60	ribe th	e da	nâno	ous waste.
Ε	ΧĄ	H٢	LE F	OR (COMPLETING SECTION IV Jahenn A	, <i>S</i> isa	numb	ers ,	X-1,	. X	2	X.3	. an	d į	X-4 be	bw,	- A (s	facility will treat and dispose of an estimated 900 pounds per year
		ala Hali	me_i dth	ete v	nge Trom leather terming and Island vill be an estimated 200 pounds per	. A44	of at	λπ. i kah w	n ai	ė.	The	, Tr	ir i t					d dispuse of three non-listed wastes. Two wastes are corrected and ignitable and there will be an estimated 100 pounds per year
- 0	<u> </u>	i i K	VVAG		reatment will be in an incinerater a	na e	*****	1	. 00			-						D. Mocesses
			A. IERC			Ç.	UNIT	╟	—			_						U. FROCESSES
Ö	W/	NG	TEN	10.	8. ESTIMATED ANNUAL QUANTITY OF WASTE	\ £	SURE	1			1 . 1	PRO	CE	22	CODE	2		2. PROCESS DESCRIPTION
į ·	(en	7 (0	r co	dei			enter code/				••		(en				٠	(if a code is not entered in D(1))
X-1	K	0	5	4	900	1	P	7	,	3	D	8	0		T	T	П	-
X-2	D	0	0	2	400	T	P	7	0	3	D	8	0	T	11	Ť	11	
X-3	g	0	0	,			او	+	ø	3	-	٦	ᇧ	H	T	\dagger	ΙΙ	
/ ·	=	ΙΨ	- 9	r * 1"	, 50	1	17	1.	v	J	. •	•	~	1		- 1		1

FORM 3 DANGEROUS WASTE PERMIT APPLICATION U.S. ENVIRONMENTAL PROTECTION AGENCY/STATE IDENTIFICATION NUMBER WA7890008967

Section III.C.. Description of Process Codes Listed in Section III.A.

The Plutonium-Uranium Extraction (PUREX) Plant, constructed in 1956, is located in the southeast corner of the 200 East Area of the Hanford Facility. The PUREX Plant was used for the recovery of uranium and plutonium from irradiated reactor fuel. Liquid-liquid processes were used to separate the plutonium and uranium from fission products and to separate the plutonium from the uranium.

The PUREX Plant consists of the 202-A Building and various support structures. The 202-A Building is a reinforced concrete structure 306.3 meters (1,005-feet) long, 36.3 meters (119-feet) wide (at its maximum), and 30.5 meters (100-feet) high with approximately 12.2 meters (40 feet) of the height below grade. The 202-A Building consists of three main structural components: (1) a thick walled, concrete canyon containing remotely operated process equipment (in cells below grade); (2) the pipe and operating, sample, and storage galleries; and (3) an annex that includes offices, process control rooms, laboratories, and the building services.

The PUREX Plant is currently undergoing a transition phase where past process solutions will be either removed from the 202-A Building in bulk for treatment, storage, and/or disposal, or treated and stored until final disposition to the Double-Shell Tank (DST) Systems. Dangerous waste activities at the PUREX Plant include the treatment and storage of regulated materials that support the transition of this treatment, storage, and/or disposal unit. Also, the 202-A Building may receive and temporarily stage mixed waste from onsite sources prior to storage in the PUREX Storage Tunnels.

The following are treatment and storage processes for the PUREX Plant.

Tol Tank E5 [19,873 liter (5,250 gallon) design capacity] - mixed waste is treated with NaOH and NaNO₂ before sending the waste to the DST System.

The concentrator [E-F11; 9,804-liter (2,590 gallon) design capacity] and tank G7 [TK G7; 56,781 liter (15,000 gallon) design capacity]- Ammoniacal mixed waste was processed in the concentrator with the ammonia distillate going to the 216-A-36B Crib before September 1987. From September 1987 to March 1990, ammoniacal waste was collected in tank G7 and treated with NaOH and NaNO2 before being transferred to the DST System. During PUREX Plant transition, the E-F11 may be used to minimize the volume of liquid waste sent to the DST System by evaporation of water from flush solutions (both regulated and nonregulated) with the distillate (nonregulated) being discharged to the atmosphere via the PUREX main stack (291-A-1). The concentrate generated in the E-F11 is treated with NaOH and NaNO, in tank F18 [19,797 liter (5,230 gallon) design capacity] or TK-G7 before transfer to the DST System. Tank G7 also will be used to treat the flush and other waste solutions before transferring them to the DST System during transition.

Section III.C. Description of Process Codes (continued)

Tank F15 [19,419-liter (5,130 gallon) design capacity] and tank F16 [19,870-liter (5,249-gallon) design capacity]— The mixed waste may be been sent to the E-F11 for volume reduction. Residual liquids are treated with NaOH and NaNO2 in tanks F15, F16, or F18 before transfer to the DST System.

SO2 Vessels storing mixed waste in the PUREX Plant are shown on the PUREX
Plant Vessel Table (page 5 of 21), which includes the vessel identification
(ID) number, tank location, and tank capacity. The total process design
capacity for tank storage is 1,239,733 liters (327,503.5 gallons).

SQ5 The designation SQ5 (storage miscellaneous) has been used to indicate that the solid mixed waste on the canyon deck and in F-Cell is stored in a containment building subject to the requirements of 40 CFR 265, Subpart DQ. The solid mixed waste on the canyon deck may consist of contaminated discarded canyon process equipment, jumpers (or isolated components thereof) or other material from various onsite sources. The solid mixed waste in F-Cell consists mainly of concrete and tank dunnage corrosion products. The process design capacity of the storage areas on the canyon deck and in F-Cell is 434 cubic meters (567 cubic yards).

PUREX PLANT VESSEL TABLE

VESSEL ID	LOCATION	CAPACITY (LITERS)
TK-05	D Cell	19,851
TK-E5	E Cell	19,873
TK-E6	E Cell	19,813
IK-F3	F Cell	19,964
	F Cell	1,132
E-F11	F Cell	9,804
TK+F15	F Cell	19,419
TK-F16	F Cell	19,870
TK-F18	F Cell	19,798
TK+G1	G Cell	18,662
TK-62	G Cell	7,064
T+G2	G Cell	8,248
TK+G5	G Ceil	55,403
	G Cell	56,781
TK-G8	G Cell	19,881
TK-H1	H Cell	19,593
T-H2	H Cell	7,003
E-H4	H Cell	10,137
. TK+J1	J Cell	19,926
TK-J3	J Celi	19,911
T+J6	J Cell	6,057
. T-J7 · ·	- J Cell	3,146
TK-J21	J Cell	1,162
T-J22	J Cell	568
T-J23	. J Ceil	393
TK-K1	K Cell	19,828
T-K2	K Cell	5,194
T-K3	K Cell	6,507
TK-K6	K Cell	19,593
T-L2	<u>L</u> Ceit	447
TK-L3	L Cell	234
T-L4	L Cell	1,987
TK-R1	R Cell	18,121
TK-R2	R Cell	6,746
T-R2	R Cell	8,282
- 7K-R7	- R Cell	35,174
ŢĶ-u3	U Cell	
TK-U4	n Ceff	31,124
TK-P4	203-A	31,184
TK-40	211-A	402,963
TK-156		247,357
	AMU apacity	1,533 1,239,733.00

For conversion, apply the following: liters to gallons - multiply liters by 0.26417

Continued from page 2. NOTE: Photocopy this page before completing if you have more than 28 wastes to list. I.D. NUMBER (entered from page 1) WA7890008567 IV. DESCRIPTION OF DANGEROUS WASTES (continued) D. PROCESSES C. UNIT OF MEA-SURE N DANGÉROUS Q WASTE NO. B. ESTIMATED ANNUAL DUANTITY OF WASTE 1: PROCESS CODES 2. PROCESS DESCRIPTION
(If a code is not entered in D(1)) ionter (anter code) WITOI TO <u> Treatment - Chemical/Storage - Tank</u> 29.937.096* --0 0 W P O 1 WPO ID IO IOI 1 through Included With Above |D|0|1|1 Storage - Miscellaneous **S05** T O 1 15.200* (Containment Building) T 0 WICIOI2 lo 0 0|5 13 ithrough lolol8 D 0 1 0 Included With Above Û * The estimated annual quantities of waste listed above represents the maximum quantities of solid dangerous waste currently treated and stored at the PUREX Plant. Future closure activities might necessitate an increase in excess of these estimates and a permit application revision could be pursued as required by dangerous waste regulations. 20 22 23 25

・ 一般の アンドル できません 一般	
Continued from the front.	
IV. DESCRIPTION OF DANGEROUS WASTES (continued)	
Tank E5 containing (1) decladding waste consisting of NH ₆ F, (NH ₆) ₂ ZrF ₆ , (NH ₆) ₂ UF ₆ , and NH ₆ NO ₃ ; (2) metathesis solutions consisting of KOH and KF; or (3) metathesis rinse and miscellaneous flushes with similar chemical makeups. All streams are treated with NaOH to a pH greater than 12, which consists mainly of NaF, KF, UO ₂ , ZrO ₂ , NH ₃ , NH ₆ OH, and NaNO ₄ . During deactivation, waste and flush solutions will be treated to obtain a pH greater than	
12 and [NO ₂] greater than 0.011 molar before transferring the waste to storage.	
The concentrator (E=F11) bottoms, containing NH,NO ₃ and NH,OH or nitric acid, are transferred to tank F18 or tank G7 and treated with NaOH and NaNO ₂ .	
Tanks F15 and F16 contain acid waste with HNO $_3$ and possibly A1(NO $_3$) $_3$, which is treated with NaOH and NaNO $_2$	
Tank_F18_and_tanks_U3_and_U4_receive_miscellaneous_waste_with a constantly changing composition consisting mainly-of-water and HNO3. Waste-is-treated-with NaOH and NaNO2 to ph_greater_than_12.	-
All tanks (refer to PUREX Plant Vessel Table on page 5 of 21) may receive and store flush solutions. Waste might be concentrated in the E-F11 and/or treated with NaOH and NaNO ₂ to pH greater than 12.	
The PUREX Plant containment building stores material that contains barium, cadmium, chromium, lead, silver, selenium and/or light-mineral-oil (WTO2) contained in oil absorbent material.	
V. FACILITY DRAWING Refer to attached drawing.	
All existing facilities must include in the space provided on page 5 a scale drawing of the facility (see instructions for more detail).	
VI. PHOTOGRAPHS Refer to attached photographs.	
All existing (sellities must include photographe (serial or ground-inval) that disarty delineste all existing etructures; existing storage, treatment and disposal ereas; and sites of future storage, treatment or disposal areas (see instructions for more detail).	
VII. FACILITY GEOGRAPHIC LOCATION This information is provided on the attached drawings and photos.	_
LATITUDE (degrees: minutes, & seconds) LONGITUDE (degrees, minutes, & seconds)	_
┝╌┧┞╌╀╼┨┡╌┸╼┨╸ ┍╌╸┩ ╒╶┸ ╼┨┡╌┸╼┨╸ ┍╌	
VIII. FACILITY OWNER	
A. If the facility owner is also the facility operator as listed in Section VII on Form 1, "General information", place an "X" in the box to the left and akip to Section below.	ıx
B. If the facility owner is not the facility operator as lieted in Section VII on Form 1, complete the following items:	
1. NAME OF FACILITY'S LEGAL OWNER 2. PHONE NO. Jame code & a	g.)
3. STREET OR P.O. BOX 4. CITY OR TOWN 5. ST. 6. ZIP CODE	_
IX. OWNER CERTIFICATION	
certify under penelty of law that I have personally examined and am familiar with the information submitted in this and all attached decuments, and that based on my Inquiry of these individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. I am aware ti there are significant panelties for submitting false information, including the possibility of fine and impresonment.	her
NAME (print or type) John D. Wagoner, Hanager DATE SIGNED	-
X. OPERATOR CERTIFICATION 2. S. Department of Energy Richland Operations Office X. OPERATOR CERTIFICATION	_
certify under penetry of law that I have personally examined only in familiar with the information admitted in this and all ettached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the lubmitted information is true, accurate, and complete. I am aware the third imprisonment. NAME (print or type) SIGNATURE	M.C.
NAME (PINT OF TYPE) SIGNATURE DATE SIGNED	_

ECL30 - 271 - ECY 030-31 Form 3

X. OPERATOR CERTIFICATION


I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.


Owner/Operator

John D. Wagoner, Mahager U/S. Department of Energy (Richland Operations Office 8/21/95


Co-operator


A. LaMar Trego, President Westinghouse Hanford Company fate






39201061.7







SECTION C-C

NOTE:

SHADED AREAS DENOTE VESSEL LOCATIONS. SEE PUREX VESSEL TABLE FOR SPECIFIC LOCATIONS.

ENCLOSURE 2

PUREX Storage Tunnels Rev. 3, 08/21/95, Page 1 of 9

Please print or type in the uncheded areas only

(Hillin areas are special for alite from Le., 12 character/inch).

(tal-in wess are specied tot and type, i.e., 12 unitractar/inch).														
DANGEROUS WASTE PERMIT APPLICATION	1. EPA/STATE I.D. NUMBER													
3 DANGEROUS WASTE PERMIT APPLICATION	WA7890008967													
FOR OFFICIAL USE ONLY APPLICATION DATE RECEIVED COMMENTS														
APPROVED (me. dev. a.w.) COMMENTS														
COST OR PENISO ASH CATON														
III. FIRST OR REVISED APPLICATION Place on "X" in the engagestate has in A or 8 below (made one box only) to indicate whether this is the first application you are a	submitting for your facility or a revised													
Place an "X" in the appropriate box in A or 8 below (mark one box only) to indicate whether this is the first application you are application. If this is your first application and you already know your facility's EPA/STATE I.D. Number, or if this is a revised at I.D. Number in Section I above.	pplication, enter your facility's EPA/STATE													
A. FIRST APPLICATION (place an "X" below and provide the appropriate date) 1. EXISTING FACILITY (See instructions for definition of "existing" facility. Complete Item below.)	CILITY (Complete Item below)													
MO. DAY YR. FOR EXISTING FACILITIES, PROVIDE THE DATE (mo., day, & yr.) MO. DAY	YR FOR NEW FACILITIES,													
0 6 1 5 6 OPERATION SEGAN OR THE DATE CONSTRUCTION COMMENCED	(ma., day, & w) OPERA- TION BEGAN OR IS EXPECTED TO BEGIN													
REVISED APPLICATION (place an "X" below and complete Section / above) X 1. FACILITY HAS AH INTERIM STATUS PERMIT 2. FACILITY HAS A FINAL PERMIT														
III. PROCESSES - CODES AND CAPACITIES A. PROCESSES - CODE - Enter the gode from the list of process codes below that best describes each process to be used at the facility. Ten lines are provided for entering														
A. PROCESS CODE - Enter the code from the list of process codes below that best describes each process to be used at the facility. Ten lines are provided for entering nodes, if more lines are needed, enter the code(s) in the space provided. If a process will be used that is not included in the list of codes below, then describe the process (including its design capacity) in the space provided on the (Section III-C).														
B. PROCESS DESIGN CAPACITY - For each code entered in column A enter the capacity of the process.														
1. AMOUNT - Enter the amount.														
2. UNIT OF MEASURE - For each amount entered in column B(1), enter the code from the list of unit measure codes below the Christ the units of measure that are listed below should be used.	nat describes the unit of measure used.													
	PRO- APPROPRIATE UNITS OF													
PROCESS CODE DESIGN CAPACITY PROCESS	PRO- CESS MEASURE FOR PROCESS CODE DESIGN CAPACITY													
Storage: Treatment:														
CONTAINER (barrel, drum, etc) SO1 GALLONS OR LITERS TANK SO2 GALLONS OR LITERS TANK SO2 GALLONS OR LITERS SURFACE IMPOUNDMENT	LITEDE DED CAU													
CURIC METERS SURFACE IMPOUNDMENT SO4 GALLONS OR LITTERS INCINERATOR	UTERS PER DAY TOS TONS PER HOUR OR													
Oleposal:	TO2 GALLONS PER DAY OR LITERS PER DAY TO3 TOMS PER HOUR OR METRIC TOMS PER HOUR: GALLONS PER HOUR OR LITERS PER HOUR													
NJECTION WELL D80 GALLONS OR LITERS LANDFIL D81 ACRE-FEET the volume that OTHER (Use for physical, chamic														
would cover one zere to a thermal or biological treatment depth of one feet; processes not ecouning in tanks.	cal, TO4 GALLONS PER DAY OR LITERS PER DAY													
depth of one feet) processes not occurring in tanks OR HECTAR-METER surface impoundments or inciner LAND APPLICATION D82 ACRES of HECTARES ators. Describe the processes in														
LITERS PER DAY SURFACE IMPOUNDMENT D84 GALLONS OR LITERS	•													
UNIT OF UNIT OF MEASURE MEASURE	UNIT OF MEASURE													
	IT OF MEASURE CODE													
i Clerki y and Skitting to the transfer of the control of the cont	RG-FEET A CTARG-METER F													
GALLONS PER DAY U LITERS PER HOUR	CTARES													
EXAMPLE FOR COMPLETING SECTION III Inhown in line accepted N-1 and X-2 below!: A feeling her time started hold 200 gallens and the other can hold 400 gallens. The feeling also has an incinerator that can burn up to 20	to tanks, one fact our gallone per hour.													
B. PROCESS DESIGN CAPACITY B. PROCESS D	ENGN CAPACITY													
L U CESS CODE N B (from list shove) R 1														
X-1 S 0 2 500 8														
-X-2 7 0 3 20 E														
7 S 0 5 24,007 C 7														
* Process Code SO5 is being used to designate the PUREX St	CONTRA TURNOTO													
as a "Miscellaneous Unit" per 40 CFR 264, Subpart X.	orage tunnets													
4 10 10 10 10 10 10 10 1														

Continued from the front.

III. PROCESSES (continued)

C. SPACE FOR ADDITIONAL PROCESS CODES OR FOR DESCRIBING OTHER PROCESS 10040 "TOA"). FOR EACH PROCESS ENTERED HERE INCLUDE DESIGN CAPACITY.

\$Q:

The PUREX Storage Tunnels are a miscellaneous unit (SO5) used for storage of mixed waste subject to the requirements of 40 CFR 264, Subpart X. The two tunnels are designed to store discarded equipment. Since being placed into service, mixed waste has been stored in the tunnels on railcars. Not all material stored in the tunnels contains mixed waste.

The construction of Tunnel 1 was completed in 1956. The tunnel is approximately 5.8 meters (19 feet) wide by 6.7 meters (22 feet) high by 107 meters (350 feet) long and provides storage space for eight railcars. Between June 1960 and January 1965, all eight railcar positions were filled and the tunnel was subsequently sealed. The combined volume of the equipment stored in Tunnel 1 is approximately 596 cubic meters (780 cubic yards). The maximum process design capacity for storage in Tunnel 1 is approximately 4,129 cubic meters (5,400 cubic yards).

The construction of Tunnel 2 was completed in 1964. Tunnel 2 is approximately 5.8 meters (19 feet) wide by 6.7 meters (22 feet) high by 512 meters (1,680 feet) long and provides storage space for 40 railcars. The first railcar mass piaced in Tunnel-2 in December 1967 and as of June 1995, 21 railcars have been placed in the tunnel. The combined volume of equipment stored on the 21 railcars presently in Tunnel 2 is approximately 1,797 cubic meters (2,350 cubic yards). The maximum process design capacity for storage in Tunnel 2 is approximately 19,878 cubic meters (26,000 cubic yards).

IV. DESCRIPTION OF DANGEROUS WASTES

- A. DANGEROUS WASTE NUMBER Enter the lour digit number from Chapter 173-303 WAG for each listed dangerous waste you will handle. If you handle dangerous wastes which are not fisted in Chapter 173-303 WAC, enter the four digit number(s) that describes the characteristics and/or the toxic contaminants of those dangerous wastes.
- 8. ESTMATED ANNUAL QUANTITY For each listed waste entered in column A actimate the quantity of that waste that will be handled on an annual basic.

 For each characteristic or texis contaminant entered in column A estimate the total annual quantity of all the non-listed waste(s) that will be handled which possess that characteristic or contaminant.
- C. UNIT OF MEASURE For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate codes are:

ENGLISH UNIT OF MEASURE	CODE	METRIC UNIT OF MEASURE	CODE
POUNDS	P	KILOGRAMS	

_il lacility records use any other unit of measure for quantity, the units of measure must be converted into one of the required units of measure taking into account the expressive density or specific gravity of the weste.

D. PROCESSES

1. PROCESS CODES:

For listed dangerous waste: For each listed dangerous waste entered in column A select the code(s) from the list of process codes contained in Section III to indicate how the waste will be stored, treated, and/or disposed of at the facility.

For non-listed dangerous wastes: For each characteristic or texic contaminent entered in Column A, select the code(a) from the list of processes that characteristic or toxic contaminent.

Section III to indicate all the processes that will be used to store, treat, and/or dispose of all the non-listed dangerous wastes that processes that characteristic or toxic contaminent.

Note: Four spaces are provided for entering process codes. If more are needed: (1) Enter the first three as described above; (2) Enter "000" in the extreme right box of Item IV-D(1); and (3) Enter in the space provided on page 4, the line number and the additional code(s).

T-2: PROCESS DESCRIPTION: If a code is not listed for a process that will be used; describe the process in the space provided on the form.

NOTE: DANGEROUS WASTES DESCRIBED BY MORE THAN ONE DANGEROUS WASTE NUMBER - Dangerous wastes that can be described by more than one Waste Number shall be described on the form as follows:

- Select one of the Dangerous Waste Numbers and enter it in column A. On the same line complete columns B, C, and D by estimating the total annual quantity of the waste and describing all the processes to be used to treat, store, and/or dispose of the waste.
- 2. __in column A of the next line enter the other Dangerous Waste Number that can be used to describe the waste. In column D(2) on that line enter "included with above" and make no other entries on that line.
- ---3. Repeat step 2-for each other Dangarous Waste Number that can be used to describe the dangerous waste,

EXAMPLE FOR COMPLETING SECTION IV Ishown in line numbers X-1, X-2, X-3, and X-4 below! • A facility will treat and dispose of an estimated 900 pounds per year of chrome shavings from leather tenning and finishing operation. In addition, the facility will treat and dispose of three non-listed wastes. Two wastes are corrosive any restricted and street will be an estimated 100 pounds per year of that waste. The other waste is correctly and ignitable and there will be in an incinerator and disposal will be in a lendfill.

	ļ				-	ļ _. .		_L													D. PROCESSES
7-ZE	W	ABI	ERC TE N		8. ESTIMATED ANNUAL QUANTITY OF WASTE	SU /ar	C. UNIT OF MEA- SURE (anter code)			1. PROCESS CODES								3	,		2. PROCESS DESCRIPTION (if a code is not entered in D(1))
X-1	ĸ	o	5	4	900	Ţ	7	Ţ	7	ر	3	O	8	0	Г	!	ī	Π	T	T	
X-2	D	O	0	2	400	ŢŢ	-	Ţ	7	0	3	٥	8	0		Ī	T	T	Т	7	-
X-3	D	o	o	1	100		•	T	7	01	3	D	8	0		1	Ī	П	T		
X-4	D	0	0	2			Ī		7	0	3	۵	8	0		·	1	T	1		included with above

Continued from page 2. NOTE: The long this page indices completing if you have more than 26 westes to list.

LD. NUMBER (entered from page 1) WA7890008857 IV. DESCRIPTION OF DANGEROUS WASTES (continued) D. PROCESSES C. UNIT OF MEA-SURE (anter code) N DANGEROUS B. ESTIMATED ANNUAL QUANTITY OF WASTE 1. PROCESS CODES 2. PROCESS DESCRIPTION IN a code-in not-antered in-D(f). ipioioi 5 454* Storage - Miscellaneous 0006 454* W C 0 2 WITO 0007 454* 8 |0 |0 | a 2,722* 00009 45* 0010 454* 0 0 1 1 680* D 0 0 1 WITIO 2 454*... Inlauded With Above 12 The estimated annual quantity of waste listed above represent the maximum quantity of waste placed in either tunnel in a given year. 16 17 16 19 20 21 22 24 25 26

PUREX Storage Tunnels

Rev. 3, 08/21/95, Page 4 of 9 Continued from the front. IV. DESCRIPTION OF DANGEROUS WASTES (continued) E. USE THIS SPACE TO LIST ADDITIONAL PROCESS CODES FROM SECTION D(1) ON PAGE 3. The waste stored in the funnels includes barium (D005), chromium (D007), cadmium (D006), lead (D008), mercury (D009), selenium (D010), silver (D011), and light mineral oil contained in oil absorption material (WT02). The silver is predominately in the form of salts and are considered ignitible (D001) because of the presence of silver nitrate (AgNO₃). The dangerous waste may be considered texic, dangerous waste (WTO2) and/or carcinogenic, dangerous waste (WCO2). V. FACILITY DRAWING Refer to attached drawing. All existing facilities must include in the space provided on page 5 a scale drawing of the facility face instructions for more detail). Refer to attached photographs. This information is provided on the attached drawings and photos. VII. FACILITY GEOGRAPHIC LOCATION LONG!TVOL 14 VIII. FACILITY OWNER A. If the facility owner is also the facility operator as facted in Section VII on Form 1, "General information", place an "X" in the box to the left and skip to Section IX B. If the facility owner is not the facility operator as listed in Section VII on Form 1, complete the following items: OWNER CERTIFICATION ! certify under paratty of law that I have personally ex-inquiry of those individuals immediately responsible for etion submitted in this and all attached desuments, and that based on my of the submitted information is true, accurate, and complete, I am aware that there ere significant penelties for su NAME (print or type) John D. Wagoner, Hanager U.S. Department of Energy Richland Operations Office X. OPERATOR CERTIFICATION I certify under penalty of law that I have personally ex-inquiry of those individuals immediately responsible for there are significant penalties for submitting folioe infer NAME (print or type) SIGNATURE DATE SIGNED

ECL30 - 271 -ECY 030-31 Ferm 3

SEE ATTACHMENT

X. OPERATOR CERTIFICATION

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.

Owner/Oderator

John D. Wagoner, Manager U.S. Department of Energy

Richland Operations Office


8/21/95

Co-operator


A. LaMar Trego, President

Westinghouse Hanford Company


1/3/95




PUREX TUNNEL NO. 1 - DETAILS




Tunnel No. 1 - Plan View




PUREX Tunnel No. 1 - Section Views





PUREX TUNNEL NO. 2 - DETAILS






PUREX Tunnels - Plan View





PUREX STORAGE TUNNELS



46*32'47" 119*31'07"

89100252-3CN (PHOTO TAKEN 1989)


PUREX PLANT (SOUTH SIDE)



46°32'57* 119°31'12*

8706243-4CN (PHOTO TAKEN 1987)


----STANDARD-5,000-GALLON TANK (TYPICAL OF E5, F15, F16, **AND F18)**



8706243-5CN (PHOTO TAKEN 1987)

TANK E5


Pipe Trench Wall - Top View



46°32'46" 119°07'58" 099948-38CN (PHOTO TAKEN 1982)

TANK F15 AND TANK F16

Pipe Trench Wall - Top View




46*32'46" 119*08'00"

(PHOTO TAKEN 1982)

TANK F18


Pipe Trench Wall - Top View



46°32'46" 1-19°08'01"

099948-74CN (PHOTO TAKEN 1982)


E-F11 CONCENTRATOR



(PHOTO TAKEN 1987)

E-F11 CONCENTRATOR

Pipe Trench Wall -- Top View




46°32'46" 119°07'59"

099948-64CH (PHOTO TAKEN 1982)

U CELL

Top of Tank U3 (Typical of Tank U4)



46°32'48" 119°07'56"


92102839-10CN (PHOTO TAKEN 1992)

U CELL

Bottom of Tanks

Tank U3

Tank U4



46*32'48"

92102839-7CN

(PHOTO TAKEN 1992)